



Republic of the Philippines
Department of Education
REGION III
BATAAN HIGH SCHOOL FOR THE ARTS

JUL 27, 2025

SCHOOL MEMORANDUM

No. **125**, s. 2025

**IMPLEMENTATION OF ALTERNATIVE DELIVERY MODE (ADM)
ON JULY 28-29, 2025**

To: Chief Administrative Officers
Chief Education Program Specialist
All School Office Personnel
Young Artists and Parents
All Others Concerned

1. Due to the impact of recent typhoons and the enhanced Southwest Monsoon (Habagat), BHSA facilities, including the electrical system, and the temporary student dormitory at PSALM acquired damages and is subjected for repairs, this Office announces the **Implementation of Alternative Delivery Mode (ADM)** on **July 28-29, 2025** for all grade levels.

2. Upon the agreement during the emergency meeting held on July 26, 2025 (9:00 am) attended by the School Director, Chiefs/Supervisors/Unit Heads of each Functional Divisions, Dorm Managers, and other concerned non-teaching personnel, this Office issue the precautionary and adaptive measures to ensure the safety and well-being of all learners and personnel.

3. DepEd Order No. 22, s. 2024 (Implementing Guidelines on the Cancellation or Suspension of Classes and Work in Schools in the Event of Natural Disasters, Power Outages/Interruptions, and Other Calamities), which authorizes school heads to suspend classes and work based on local assessments of safety and accessibility, the following measures shall be implemented:

- **Alternative Delivery Mode (ADM)** shall be implemented for all learners on **July 28-29, 2025**.
- **Face-to-face classes** shall resume on **July 30, 2025**, subject to favorable weather conditions.

A separate memorandum shall be issued for the extension of ADM if condition did not meet.



Republic of the Philippines
Department of Education

REGION III

BATAAN HIGH SCHOOL FOR THE ARTS

4. In line with this, **Academic Affairs Division** is requested to monitor smooth coordination and implementation of ADM while **Student Affairs Division** shall ensure immediate information dissemination and communication with all stakeholders regarding this memorandum.
5. Enclosed are the photo documentation and the initial report of damages sustained by the school, in support of the decision to suspend classes.
6. For queries or further coordination, kindly send an email to **bhsa@deped.gov.ph**.
7. Immediate and wide dissemination of this memorandum is directed.

MIA ARIANA P. TANCIONGCO, PhD

Director III
School Director

Encl.:
Reference: as stated
To be indicated in the Perpetual Index
Under the following subjects

ADM
WORK ARRANGEMENT

WFH/SKELETAL
SUSPENSION

OSD01/OSD04 July 27, 2025



Republic of the Philippines
Department of Education
REGION III
BATAAN HIGH SCHOOL FOR THE ARTS

Enclosure 1 of School Memorandum No. __, s. 2025

PHOTO DOCUMENTATION

**VILLA A9 SIDE
GUTTER**



**VILLA D17 SIDE
GUTTER**




**VILLA D21 SIDE
GUTTER**







Republic of the Philippines
Department of Education
REGION III
BATAAN HIGH SCHOOL FOR THE ARTS





Villa D18 gutter






Republic of the Philippines
Department of Education
REGION III
BATAAN HIGH SCHOOL FOR THE ARTS

SLIPPERY PAVEMENTS





Republic of the Philippines
Department of Education
REGION III
BATAAN HIGH SCHOOL FOR THE ARTS



The damaged ceiling in the conference room caused by persistent water leakage from heavy rainfall.



Republic of the Philippines
Department of Education
REGION III
BATAAN HIGH SCHOOL FOR THE ARTS



A ceiling water leak in the admin office triggered an electrical wiring fuse, posing a serious safety hazard.





Republic of the Philippines
Department of Education
REGION III
BATAAN HIGH SCHOOL FOR THE ARTS



A ceiling leak in the dormitory caused flooding and a burnt electrical outlet due to water exposure.





Republic of the Philippines
Department of Education
REGION III
BATAAN HIGH SCHOOL FOR THE ARTS



The entrance to the administrative building was flooded due to continuous water leakage from the ceiling.





Republic of the Philippines
Department of Education
REGION III
BATAAN HIGH SCHOOL FOR THE ARTS



A broken glass window in the arts building was due to strong winds.

